Oil Field Environmental Incident Summary

Responsible Party: CONTINENTAL RESOURCES, INC. **Well Operator:** CONTINENTAL RESOURCES, INC.

Well Name: DOBS CTB

Field Name: CEDAR HILLS Well File #:

 Date Incident:
 5/5/2016
 Time Incident:
 10:00
 Facility ID Number:
 413779-03

 County:
 SLOPE
 Twp:
 133
 Rng:
 106
 Sec:
 32
 Qtr:
 SE SE

Location Description:

Submitted By: Patrick Skillestad Received By:

Contact Person: Patrick Skillestad

PO BOX 268870

OKLAHOMA CITY, OK 73126

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained in Dike: Yes - On Constructed Well SiteReported to NRC: NoSpilledUnitsRecoveredUnitsFollowupUnitsOil3Barrels3Barrels3barrels

Brine Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 10/14/2016 Clean Up Concluded: 5/13/2016

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

Location soil

Action Taken or Planned:

Contaminated material will be removed and disposed of.

Wastes Disposal Location: Little Missouri Special Landfill

Agencies Involved:

Updates

Date: 5/5/2016 Status: Reviewed - Assigned to Other Agency Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to equipment failure, was contained on the constructed well site according to the report. NDIC retains oversight.

Date: 6/6/2016 Status: Correspondence Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Bill Suess sent a No Further Action letter dated June 6, 2016.